

Roads / Sidewalks

- a) Grade 45 Ave and 51 St in industrial park
- b) Repair back alleys, fill potholes and gravel as required
- c) Fill in with cold mix along gutter at Post Office and pack

Water/Wastewater

- a) The town experienced no power disruptions since last report all systems good
- b) TSS, BOD and CBOD tests taken and annual lagoon release started
- c) Pumphouse and Lift station furnaces inspected
- d) Replaced 2 cc valve topboxes and tested valves on 47 Ave
- e) Water service restored to residential property as per request
- f) Replaced old water meter at residential property as per admin request
- g) Monitoring south side water pressure and cl2 levels
- h) Monitoring distribution flow rates
- i) Investigate high consumption complaint and check meter
- j) Barrel fill at truck fill serviced and repaired
- k) Lift station generator test
- I) Begin working on AB ENV annual water and wastewater reporting
- m) Clean sanitary lift station wet cell
- n) Sewer auger residential sanitary line as per request
- o) Hydro jetting and Vac of sanitary and storm lines (Urlacher)
 - a. 57ave west of County Shop (lots of grease and oil in line added 1 pail High heat degreaser and 2 pails of Flow mate (citrous) degreaser and flushed line with full load of water at end of day
 - b. 44st to 49Ave
 - c. 49 Ave to 46 Street
 - d. 45 Street to 49 Ave
 - e. 47 Ave east of 46 Street
 - f. 48street north from 53 Ave (250') mid block to 54 Ave
 - g. 47 Ave alley to 48 Ave storm water cross over
 - h. 47 Ave storm water line to south side of Mennonite school 232' unable to reach school ditch

Other

- a) Install new gate posts at Geleta Park entrance and between Rec centre and the Hall
- b) Drain water from packers, street sweeper and remove batteries
- c) First calls complete and marked for stump removal at the east side of museum and alley at Cougar Tire
- d) Install new skid steer and grader tires
- e) Replace old hydraulic lines on Volvo tamper
- f) Complete service requests

